



## Technical Service Bulletin 146

**Date:** May 3, 2007

**Subject:** 13953 Shift Cable Replacement

**Models Affected:** **6007R-01 6006R-09**

**Description of Problem:** Existing cable may malfunction, causing the kart to no longer be capable of shifting into reverse.

**Solution:** Replace cable with new version.

**Procedure:** Please follow the attached instructions.